

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

FU882  
WSW  
> 1  
1.183 mi.  
6244 ft.

VAULT 43551  
WEST 33RD ST/SURF AVE  
BROOKLYN, NY

NY Spills S103573363  
N/A

Site 4 of 4 in cluster FU

Relative:  
Higher

Actual:  
8 ft.

SPILLS:

Name: VAULT 43551  
Address: WEST 33RD ST/SURF AVE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9809227 / 2002-10-31  
Facility ID: 9809227  
Facility Type: ER  
DER Facility ID: 205006  
Site ID: 250106  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: C4  
SWIS: 2401  
Spill Date: 1998-10-23  
Investigator: CAENGELH  
Referred To: Not reported  
Reported to Dept: 1998-10-23  
CID: 366  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1998-10-23  
Spill Record Last Update: 2002-10-31  
Spiller Name: Not reported  
Spiller Company: CON ED  
Spiller Address: 4 IRVING PL  
Spiller Company: 001  
Contact Name: Not reported  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was ENGELHARDT 15 GALLONS OF OIL. 120754 IS THIRD VAULT IN STRING OF CONNECTED VAULTS. SEE 9809222 Con Ed e2mis #120759: D.HEARNS50839 O.S.NETWORKS REPORTS FOUND APPROXIMATELY 15 GALLONS OIL ON 1000 GALLONS WATER. THIS VAULT COMMUNICATES TO V4402. NO SIGN OF SUMP PUMP. PRESSURE TESTED UNIT -- TESTED O.K. PCB READING = 12PPM. CANNOT SEE WHERE OIL COMING FROM. SEE INCIDENT#120754 FOR FURTHER INFORMATION. NO SAMPLE TAKEN -- RESULTS FROM V4402 TO BE USED. NOTIFIED CONSTANTINE OF C.I.G. AT 13:16. 10/24/98-1700HRS--CLEANUP COMPLETED TAG 06774 REMOVED HOLE MAKES WATER."  
Remarks: "PRODUCT LEAKED FROM OTHER VAULT. CON ED TO CLEAN. REF 9809222. CON ED #120759."

All Materials:

Site ID: 250106  
Operable Unit ID: 1070360  
Operable Unit: 01  
Material ID: 316684  
Material Code: 0020A  
Material Name: transformer oil

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported